

UNITED STATES NUCLEAR REGULATORY COMMISSION REGION III 799 ROOSEVELT ROAD GLEN ELLYN, ILLINOIS 60137

Docket No. 50-409

Dairyland Power Cooperative ATTN: Mr. F. W. Linder General Manager 2615 East Avenue - South La Crosse, WI 54601

SEP (1979

TIC

Gentlemen:

With this Information Notice the Nuclear Regulatory Commission is extending an existing mechanism previously used for informing facility licensees of significant operating events to include informing operator licensees of significant events which could impact on conditions of their NRC licenses. This Information Notice is being reissued to correct a word omission and a punctuation error that, when taken together, completely changed the intent of a statement. The changed statement is underlined in the text of the Information Notice.

It is requested that the facility licensee provide copies of this Information Notice to all NRC licensed individuals at the facility. No specific response is requested at this time. If you have questions regarding this matter please contact the Director of the appropriate NRC Regional Office.

Sincerely,

Gen W. Roy

James G. Keppler Director

1136 004

Enclosure: IE Information Notice No. 79-20, Rev. 1

Conversional Superior Superior

7910020 196

SSINS: 6870 Accession No: 7908220108

UNITED STATES NUCLEAR REGULATORY COMMISSION OFFICE OF INSPECTION AND EMFORCEMENT WASHINGTON, D.C. 20555

September 7, 1979

IE Information Notice No. 79-20 Rev. 1

÷...

NRC ENFORCEMENT POLICY - NRC LICENSED INDIVIDUALS

Background:

. .

In the past, NRC licensed individuals have been cited by the NRC for failure to comply with the conditions of their licenses. These items of noncompliance can generally be characterized as serious of repeated failures to follow reactor operating procedures. Two recent events involving the radiation overexposure of NRC licensed individuals through their violation of utility procedures, facility Technical Specifications and the Code of Federal Regulations have raised questions about the exercise of their responsibilities.

The purpose of this Information Notice is two-fold:

- (1) To remind the NRC licensed individuals of their reconsibilities, not only in the proper operation of the facility controls, i compliance with the facility administrative procedures, and
- (2) To summarize the enforcement sanctions available to the NRC for use against licensed individuals.

Description of Circumstances:

Responsibilities

Facility licensees are charged with the responsibility to design, construct and operate their plants in accordance with NRC requirements to assure that public health and safety are protected. The role of NRC licensed individuals is no less important in the overall Regulatory scheme. The NRC recognizes that timely actions by NRC licensed individuals are an important part of safety. Reliance on these actions is a part of the defense-in-depth concept. Specifically, the NRC requires that:

 Only licensed operators are permitted to manipulate the controls that directly affect reactivity

(2)	Licensed operators are requir all times during the operatio	DUPLICATE DOCUMENT
	1136 005	Entire document previously entered into system under:
		ANO 7908220108
		No. of pages: 5