

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

1 P A B V S 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T
0 1 REPORT SOURCE L 6 0 5 0 0 0 3 3 4 7 0 8 2 7 7 9 8 0 9 2 7 7 9 9
8 60 61 DOCKET NUMBER 62 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During a load increase, at 99 percent power, the Channel 3 Overpower Delta Temperature
0 3 alarm was received. At 1830 hours, the loop bistables were tripped. The loop was
0 4 calibrated and returned to service at 1630 hours on 8/29/79. The health and safety of
0 5 the general public were not jeopardized as redundant instrument loops were available
0 6 and the loop was protecting in the conservative direction.

0 9 SYSTEM CODE I A 11 CAUSE CODE D 12 CAUSE SUBCODE Z 13 COMPONENT CODE I N S T R U 14 COMP. SUBCODE P 15 VALVE SUBCODE Z 16
8 9 10 11 12 13 14 15 16
17 LER/RO REPORT NUMBER 7 9 21 22 EVENT YEAR 7 9 23 SHUTDOWN METHOD Z 20 Z 21 24 SEQUENTIAL REPORT NO. 0 2 6 26 27 OCCURRENCE CODE 0 3 28 29 REPORT TYPE L 30 31 REVISION NO. 0 32
33 ACTION TAKEN E 18 G 19 34 FUTURE ACTION Z 20 Z 21 35 EFFECT ON PLANT Z 20 Z 21 36 SHUTDOWN METHOD Z 20 Z 21 37 HOURS 0 0 0 0 40 41 ATTACHMENT SUBMITTED N 23 42 NPRD-4 FORM SUB. N 24 43 PRIME COMP. SUPPLIER N 25 44 COMPONENT MANUFACTURER W 1 2 0 47 48

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The instrument loop was miscalibrated as a result of not having the current RTD
1 1 calibration data in the surveillance test. The hot leg RTD was replaced during a
1 2 previous outage and new calibration data was obtained. However, the new data was not
1 3 included in the loop calibration procedure. Maintenance procedures will be revised to
1 4 insure revisions are placed in controlled procedure file.

5 FACILITY STATUS F 28 0 9 9 29 10 % POWER 12 13 OTHER STATUS N/A 30 METHOD OF DISCOVERY A 31 45 DISCOVERY DESCRIPTION Operator observation 32
8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

6 ACTIVITY CONTENT Z 33 Z 34 10 RELEASED OF RELEASE 11 AMOUNT OF ACTIVITY N/A 35 LOCATION OF RELEASE N/A 36
8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

7 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION N/A 39
8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

8 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION N/A 41
8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

9 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION N/A 43
8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

0 PUBLICITY ISSUED N 44 DESCRIPTION N/A 45
8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

NAME OF PREPARER J. A. Werling PHONE: 412-643-1258

1083 346

7910030496

NRC USE ONLY