

U.S. NUCLEAR REGULATORY COMMISSION
OFFICE OF INSPECTION AND ENFORCEMENT

Region I

Report No. 70-820/79-12

Docket No. 70-820

Safeguards Group 1

License No. SNM-777 Priority 1

Category UR

Licensee: United Nuclear Corporation

Wood River Junction, R.I. 02894

Facility Name: UNC Recovery Systems

Inspection at: Wood River Junction, Rhode Island

Inspection conducted: May 21 - 25, 1979

Inspectors: A. Gody for
H. Zibulsky, Safeguards Chemist

8/21/79
date signed

A. Gody
A. Gody, Safeguards Chemist

8/21/79
date signed

Approved by: James Joyner
J. H. Joyner, Chief, Nuclear Material
Control Support Section, Safeguards Branch

date signed

8/22/79
date signed

Inspection Summary:

Inspection on May 21 - 25, 1979 (Report No. 70-820/79-12)

Areas Inspected: Routine, announced inspection by regional based inspectors of nuclear material control and accounting in the areas of measurement and statistical controls and export verification. The inspection involved 60 inspector hours on site by two NRC regional based inspectors.

Results: In the areas inspected, no apparent items of noncompliance were identified.

1143 025