



Columbus Laboratories
505 King Avenue
Columbus, Ohio 43201
Telephone (614) 424-6424
Telex 24-5454

September 12, 1979

Mr. A. B. Davis, Chief
Fuel Facility and Materials Safety Branch
U.S. Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Dear Mr. Davis:

This is in response to your letter of August 29, 1979, regarding the inspection of our licensed activities conducted by your Messrs. C. C. Peck and D. E. Miller on August 7-10, 1979.

Please be advised that the deviation identified in the report has been corrected. The new stack monitoring system at the Hot Cell has been installed and is in operation. Installation and operation of the system was completed on August 15, 1979.

We trust this action is satisfactory and resolves the deviation.

Very truly yours,

Harley L. Toy
NRC Licensing Coordinator

HLT:lba

1143, 082

7 91 0120

046
Q

SEP 17 1979