

FILE: RR 2 (NP-33-78-133)

October 13, 1979

Docket No. 50-346 License No. NPF-3

Mr. James C. Keppler Regional E ector, Region III Office of spection and Enforcement U. S. Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

Enclosed are three copies of Licensee Event Report 78-114 and the supplemental information sheet which have been updated. The revisions to the report are indicated by a "2" in the left margin of the report.

Please replace your previous copies of Licensee Event Report 78-114 with the attached revised copies.

Yours truly,

TenDon

Terry D. Murray Station Superintendent Davis-pesse Nuclear Power Station

TDM/1jk

cc: Dr. Ernst Volgenau, Director Office of Inspection and Enforcement Encl: 30 copies LER 78-114, Rev. 2

> Mr. William G. McDonald, Director Office of Management Information and Program Control Encl: 3 copies LER 78-114, Rev. 1

1173 099

THE TOLEDO EDISON COMPANY EDISON PLAZA 300 MADISON AVENUE

TOLEDO, OHIO 43652 7910220294