

JUN 20 1973

FS&EB ACTION CONTROL FORM

- A. Action Code CDR#122
 Name of Licensee and Facility Metropolitan Edison Co. (Three Mile Island 1 & 2)
 Docket No. or License No. 50-289 & 50-320
 Title _____
 Origin CDR Report (licensee) Date Rec'd 6/15/73
- B. FS&EB Branch Coordinator:
 Bryan _____ Dreher X
 Ellis _____ Paulus _____
 Completion Requested by _____
- C. Action Requested of:
 ADREMP _____ M&PPOB _____ EPB _____ RPB _____ ADCO X
 OB _____ CB _____ TAB _____ OOE _____ Region _____
 Date Requested 6/19/73 Completion Requested by _____
 Reference Letter J. G. Miller (Met. Ed.) to F. E. Kruesi dated 6/13/73.

- D. Action Requested '
 In accordance with PI 0600/6, "Construction Deficiency Reporting" the Metropolitan Edison Company (Three Mile Island 1 & 2) deficiency report of 6/13/73, covering incomplete documentation for welding filler electrodes used for the manual metal arc process by Babcock Wilcox, Mt. Vernon, Ohio, on Units 1 & 2 reactor vessels, is being assigned to ADCO for evaluation of the technical adequacy of the corrective action being taken and final resolution of the deficiency.
- E. Date Action Completed _____
 Close-out (Date & Method) _____
 Comments: If completion date is not consistent with your work schedule, please let us know.

D. F. Knuth
 D. F. Knuth, Deputy Director
 for Field Operations
 Directorate of Regulatory Operations

1584 070

cc: J. P. O'Reilly, RO:1

7911080672