

ENCLOSURE

DESCRIPTION OF VIOLATION

Metropolitan Edison Company
Docket No. 50-289

One of the activities under your license appears to be in violation of AEC regulations, as indicated below:

Criterion II of Appendix B of 10 CFR Part 50 states in part that: "The applicant shall establish at the earliest practicable time, consistent with the schedule for accomplishing the activities, a quality assurance program which complies with the requirements of this Appendix. This program shall be documented by written policies, procedures or instructions . . ."

Contrary to the above, preoperational tests of safety related systems are being written, reviewed, approved and conducted without benefit of an approved quality assurance program.

1566 201

7911110005