



UNITED STATES  
ATOMIC ENERGY COMMISSION  
DIVISION OF COMPLIANCE  
REGION I  
970 BROAD STREET  
NEWARK, NEW JERSEY 07102

201 645-3942

December 3, 1971

J. B. Henderson, Chief, Reactor Construction  
Branch, Division of Compliance, HQ

METROPOLITAN EDISON COMPANY, THREE MILE ISLAND 1 AND 2  
CO REPORT NO. 50-289/71-05, 50-320/71-05

The subject inspection report is forwarded for information.

No items of nonconformance were identified during this inspection; however, the licensee's QA organization appears to be weak and disorganized, and it is apparent that changes are being made to strengthen it. It is anticipated that an in-depth inspection of the implementation of the QA/QC program and a review of project logs and records will be performed at an early date.

E. M. Howard  
Senior Reactor Inspector

Enclosure:  
Subject Inspection Report

cc: E. G. Case, DRS (3)  
R. S. Boyd, DRL (2)  
R. C. DeYoung, DRL (2)  
D. J. Skovholt, DRL (3)  
H. R. Denton, DRL (2)  
A. Giambusso, CO  
R. H. Engelken, CO  
L. Kornblith, Jr., CO  
Regional Directors, CO  
DR Central Files

1586 033

7911110121

9