

APPENDIX A

NOTICE OF VIOLATIONS

Metropolitan Edison Company
P. O. Box 542
Reading, Pennsylvania 19603
Docket No. 50-289

Based on the results of the NRC inspection conducted on September 17-19, 1971, it appears that one of your activities was not conducted in full compliance with the conditions of your NRC Facility License No. DPR-50, as indicated below:

Contrary to Section 6.5.c of the Appendix B, Technical Specifications, notifications were not made to the Commission by telephone and telegraph within 24 hours on two occasions in which the Limiting Conditions for Operation were exceeded and the required followup written reports were not submitted within 7 days of the occurrences.

This item is a deficiency.

Other deficiencies identified through your internal audit program which were reported in a timely manner and corrected are identified in the inspection report. No additional information is needed for these items at this time.

1586 058

7011110/35