

LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CON'T

0	1
7	8

REPORT SOURCE

X	6	0	5	0	-	0	2	9	3	7	1	1	1	9	7	9	8	1	1	2	7	7	9	9		
60	61	DOCKET NUMBER										68	69	EVENT DATE					74	75	REPORT DATE					80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

SYSTEM CODE 0 9		CAUSE CODE X X		CAUSE SUBCODE Z		COMPONENT CODE Z Z Z Z				COMP. SUBCODE Z		VALVE SUBCODE Z					
7	8	9	10	11	12	13	14	15	16	17	18	19	20				
LER/RO REPORT NUMBER 7 9		EVENT YEAR 7 9		SEQUENTIAL REPORT NO. 0 4 1		OCCURRENCE CODE 0 4		REPORT TYPE T		REVISION NO. 0							
21	22	23	24	25	26	27	28	29	30	31	32						
ACTION TAKEN Z		FUTURE ACTION Z		EFFECT ON PLANT Z		SHUTDOWN METHOD Z		HOURS 0 0 0 0		ATTACHMENT SUBMITTED N		NPRD-4 FORM SUB. N		PRIME COMP. SUPPLIER Z		COMPONENT MANUFACTURER Z 9 9 9	
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
1	5	C	28	1	0	0	29	N.A.	Notification by Environmental Lab.
ACTIVITY CONTENT		RELEASED OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE			
1	6	Z	33	Z	34	N.A.			
PERSONNEL EXPOSURES		NUMBER		TYPE		DESCRIPTION			
1	7	0	0	0	37		38	N.A.	
PERSONNEL INJURIES		NUMBER		DESCRIPTION					
1	8	0	0	0	40		41	N.A.	
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION					
1	9	Z	42		43	N.A.			
PUBLCITY ISSUED		DESCRIPTION							
2	0	N	44		45	N.A.			

PHONE: 617-746-7900