

LICENSEE EVENT REPORT

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CONTROL BLOCK: ①

⑦ ⑧ ⑨ GAEH ⑭ ⑮ 0000000000000000 ⑰ ⑱ 411111 ⑳ ㉑ ㉒

⑦ ⑧ 01 ㉓ L ⑥ ⑦ 050000321 ㉔ 070779 ⑧ ⑨ 120579 ㉕

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES ⑩

⑦ ⑧ ⑨ 02 | During normal operation, Licensee Event Report No. 50-321/1979-039 was deemed to re-
 ⑦ ⑧ ⑨ 03 | quire prompt notification as per section 6.9.1.8 of the Technical Specifications. The
 ⑦ ⑧ ⑨ 04 | RO telegram was not transmitted by 2400 hours on 11-7-79, which was when it was due.
 ⑦ ⑧ ⑨ 05 | This is a non-repetitive occurrence. No threat to the health or safety of plant
 ⑦ ⑧ ⑨ 06 | personnel or the general public was posed by this event.
 ⑦ ⑧ ⑨ 07 |
 ⑦ ⑧ ⑨ 08 |

⑦ ⑧ ⑨ 09 SYSTEM CODE ZZ ⑪ CAUSE CODE A ⑫ CAUSE SUBCODE X ⑬ COMPONENT CODE ZZZZZZZZ ⑭ COMP. SUBCODE Z ⑮ VALVE SUBCODE Z ⑯

⑰ LER-RO REPORT NUMBER 79 ⑳ SHUTDOWN METHOD ㉑ SEQUENTIAL REPORT NO. 092 ㉒ OCCURRENCE CODE 03 ㉓ REPORT TYPE L ㉔ REVISION NO. 0 ㉕

ACTION TAKEN G ⑱ FUTURE ACTION Z ⑲ EFFECT ON PLANT Z ㉖ SHUTDOWN METHOD Z ㉗ HOURS 0000 ㉘ ATTACHMENT SUBMITTED Y ㉙ NRD-4 FORM SUB. N ㉚ PRIME COMP. SUPPLIER Z ㉛ COMPONENT MANUFACTURER ZZZZ ㉜

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS ㉞

⑦ ⑧ ⑨ 10 | This event occurred because of a breakdown of the commission's telecopy machine along
 ⑦ ⑧ ⑨ 11 | with error by GPCo personnel in failing to advise plant management that transmission
 ⑦ ⑧ ⑨ 12 | was not possible so that other forms of communication could be pursued. The telecopy
 ⑦ ⑧ ⑨ 13 | operator's log has been revised to include a check-off section that directs the oper-
 ⑦ ⑧ ⑨ 14 | ator to return any document to the originator (continued)

⑦ ⑧ ⑨ 15 | FACILITY STATUS E ㉞ % POWER 100 ㉟ OTHER STATUS NA ㊱ METHOD OF DISCOVERY Z ㊲ DISCOVERY DESCRIPTION Personnel Observance ㊳

⑦ ⑧ ⑨ 16 | ACTIVITY Z ㊴ CONTENT Z ㊵ AMOUNT OF ACTIVITY NA ㊶ LOCATION OF RELEASE NA ㊷

⑦ ⑧ ⑨ 17 | PERSONNEL EXPOSURES NUMBER 00 ㊸ TYPE Z ㊹ DESCRIPTION NA ㊺

⑦ ⑧ ⑨ 18 | PERSONNEL INJURIES NUMBER 000 ㊻ DESCRIPTION NA ㊼

⑦ ⑧ ⑨ 19 | LOSS OF OR DAMAGE TO FACILITY TYPE Z ㊽ DESCRIPTION NA ㊾

⑦ ⑧ ⑨ 20 | PUBLICITY ISSUED N ㊿ DESCRIPTION NA ㊽

POOR ORIGINAL

1552 328

7912130436

Georgia Power Company
Plant E. I. Hatch
Baxley, Georgia 31513

Cause Description and Corrective Actions (continued)

by 1600 hours on the date submitted if transmission cannot be completed.

1552 529