



Public Service Company

16005 Road 19 1/2, Platteville, Colorado 80651

CENTRAL FILES
PDR:HQ
LPDR
TIC
NSIC

November 1, 1979
Fort St. Vrain
Unit No. 1
P-79260

Mr. Karl V. Seyfrit
U. S. Nuclear Regulatory Commission
Region IV
Office of Inspection and Enforcement
611 Ryan Plaza Drive
Suite 1000
Arlington, Texas 76012

Docket No. 50-267

RE: IE Bulletin 79-23

Gentlemen:

In response to IE Bulletin No. 79-23 we offer the following:

1. No circuits exist between the neutral of the EPT or CPT to the generator neutral on our installation.
2. We will have completed a test as described in the bulletin (action item no. 2) by January 31, 1980.

It should be noted that the unit installed at Fort St. Vrain was previously installed at another of PSCo's generating stations where it sustained continuous full-load operation for several days at a time on numerous occasions. No difficulties were experienced with the EPT's. This operation is not satisfactorily documented however, so we are scheduling an appropriate test.

Sincerely,

C. K. Millen
Senior Vice President

CKM:dkm

1591 014

7912170 201