TEXAS PIPE BENDING OF PUERTO RICO, INC

A SUBSIDIARY OF THE BENDIX CORPORATION PREFABRICATED PIPING - PIPE BENDS - PIPE COILS - WELDED HEADERS OFFICES & PLANTS HOUSTON, TEXAS AND PONCE, PUERTO RICO

> POST OFFICE BOX 7103 · PONCE, PUERTO RICO 00731 TELEPHONE 809 • 844-4385

November 30, 1979

United States Nuclear Regulatory Commission Region II 101 Marietta St. N.W. Suite 3100 Atlanta, Georgia 30303

Attention: Mr. J.T. Sutherland Chief Fuel Facility and Materials Salety Branch

Reference: Letter dated 11-14-79 relative to inspection of our facilities and infractions.

Dear Mr. Sutherland:

In reference to your letter stated above, we would like to assure you that any records or procedures that were viewed at the time of inspection as being insufficient have been corrected and are up-to-date. A discussion of activities relative to each item listed on your "notice of viciation" sheet follows:

- A. Pocket dosimeters are read daily and recorded as specified in regulations.
- B. Copies of operating procedures have been posted and are available for review.
- C. Records relative to surveys to assure sealed source is in its shielded positions prior to securing the exposure device have been kept and are up-to-date.

Should you have any further comments, kindly advise.

Sincerely

TEXAS PIPE BENDING CO. OF P.R.

VILLAT COPP

Mala

Michael Jarrell Manager of Plant Services

2176 -02 2912260 170