

APPENDIX A

NOTICE OF VIOLATION

EG&G, Incorporated
Salem, Massachusetts 01970
License No. 20-02804-01

Docket No. 30-4625

Based on the results of an NRC inspection conducted on August 15, 1979, it appears that certain of your activities were not conducted in full compliance with NRC regulations as indicated below:

- A. 10 CFR 20.201(b) requires that you make such surveys as may be necessary for you to comply with all sections of Part 20.
1. Contrary to this requirement, as of August 15, 1979, the day of the inspection, you failed to make such surveys as were necessary to assure compliance to 10 CFR 20.103, "Exposure of individuals to concentration of radioactive material in restricted areas." Specifically, no surveys of airborne radioactivity were conducted in your facility where carbon-14 is currently being used for production.
 2. Contrary to this requirement, as of August 15, 1979, the day of the inspection, you failed to make such surveys as were necessary to assure compliance to 10 CFR 20.103, "Exposure of individuals to concentration of radioactive material in restricted area." Specifically, you did not routinely make surveys to determine the amount and distribution of removable contamination in areas where Nickel-63 was handled.

These are infractions.

2178 204