



Don Clark
Basin Surveys, Inc.

Telephone 472-2460 P. O. Box 566
Buckhannon, W. Va.

26201

16 November 1979

United States
Nuclear Regulatory Commission
Region II
101 Marietta St., N.W., Suite 3100
Atlanta, Georgia 30303

RII : RAB
47-13796-01

Mr. J. T. Sutherland:

Please be advised that I am in receipt of your letter, dated 29 October 1979, referring to the inspection of our R/A Materials storage building. We are indeed in violation of our license and I am writing, as per your instructions, as to what corrective steps I will take to rectify this situation.

On, or before, 30 December 1979 I will have initiated a program to add shielding around one source that was causing the problem and install more adequate shielding within the building itself. Surveys shall be made of the storage area as required and the "Notice to Employees" has already been posted.

Please advise if this is not adequate.

2178 538

Sincerely,

Donald E. Clark
President
Basin Surveys, Inc.

CC/cc

c.c.: Mr. Turner, Mr. Corder

RAB
Telephone conversation with C. Corder
on 12/20/79

Should be completed by 12/30/79.

Building new shield for Ra²²⁶ source, and adding sand filled concrete blocks to shield

8001020 **675**
OFFICIAL COPY