

NORTHERN MEDICAL IMAGING, INC. formerly Northern Radioisotope Laboratory, Inc. 102 West 26th Street Bemidji, Minnesota 56601 (218) 751-4165 JAMES R. BROWN, M.D. Medical Consultant LARRY R. ODELL, R.T. Manager

December 14, 1979

Mr. John E. Boyer Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, IL 60137

Dear Mr. Boyer:

We are responding in reference to the IE Bulletin #79-19, 1 through 8.

Item 1

We do have on record a current set of DOT and NRC regulations.

Item 2, 3, 4, 5, 6, and 7

They are all covered in NMI's current Second Revision Radioisotope Safety and Procedure Manual under the pertinent section. I would refer you to the Table of Contents.

NMI has sent to your office two copies of this manual as part of our License #22-16328-01 Renewal Application dated December 1, 1979.

Item 8

A complete review of our logs and radioactive storage area was done in November, 1979 as part of our renewal application procedure by the management team of NMI. We feel that this will meet your requirements for a management controlled audit of our activities associated with the transfer, packaging, and transport of low level radioactive waste.

Sincerely,

Larry R. Odell General Manager

## 2180 212

jhb

DEC 17 1979

8001 0300