

APPENDIX A

NOTICE OF VIOLATION

Framingham State College  
Framingham, Massachusetts 01701  
License No. 20-13956-01

Based on the results of an NRC inspection conducted on September 24, 1979, it appears that one of your activities was not conducted in full compliance with NRC regulations as indicated below.

10 CFR 30.3 requires that you receive, possess and use byproduct material only as authorized by a valid NRC License. Your NRC License Number 20-13956-01 expired on February 29, 1976.

Contrary to this requirement, as of the date of the inspection, September 24, 1979, you possessed 120 mCi of tritium, a possession not authorized by a valid NRC license.

This is an infraction.

2181 283

8001040 477