

DISTRIBUTION

Central Files

PTRB Reading

SHanauer

JKramer

JZwolinski

DZiemann

DBeckham

BSiegel

DRoss

PCheck

BSheron

JGuttman

TSpeis

Mr. Roger Newton, Chairman
Westinghouse Owners Group
Procedures Subcommittee
Wisconsin Electric Power Company
231 W. Michigan
P. O. Box 2046, Room 320
Milwaukee, Wisconsin 53201

DEC 17 1980

Dear Mr. Newton:

As discussed during our November 12, 1980 meeting in Bethesda, the Westinghouse Owners Group (WOG) should provide the staff with a basis document for the emergency procedure guidelines. If this document is not available at this time, your response should include a commitment to provide it within a time frame that is mutually acceptable to the staff and the WOG.

With regard to your presentations at the November 12, 1980 meeting, we have identified two general concerns that will require resolution between the staff, WOG and Westinghouse during the course of our review. These are: (1) the interactions between the Reactor Coolant System and the containment during the limiting events as this does not appear to be addressed in your analyses and (2) the lack of transition instructions or guidelines between the EOI's and the E²OI's in the case of subsequent or multiple failures as identified in Section I.C.1 of NUREG-0737.

Based on our discussions during the meeting, we will review WCAP9691 to determine its adequacy as part of your submittal to meet the requirements of Item I.C.1 of NUREG-0737 for reanalysis of transients and accidents. We plan to have completed a preliminary review by the end of February 1981.

Sincerely,

Original signed by
Stephen H. Hanauer, Director
Division of Human Factors Safety

RD 8-2
W

8102270351

DSI:DIR
DRoss
12/16/80

SHHanauer
12/17/80

OFFICE	DHFS:PTRB	DHFS:PTRB	DHFS:PTRB	DSI:PS:RSB	DSI:PS:RSB	DSI:PS:RSB
SURNAME	BSiegel	DHBeckham	DLZiemann	BSheron	TSpeis	PCheck
DATE	12/15/80	12/15/80	12/15/80	12/15/80	12/15/80	12/16/80