



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION V  
1990 N. CALIFORNIA BOULEVARD  
SUITE 202, WALNUT CREEK PLAZA  
WALNUT CREEK, CALIFORNIA 94596

TEC  
TEC

JUN 19 1979

Docket No. 50-243

Oregon State University  
Corvallis, Oregon 97331

Attention: Dr. C. H. Wang  
Reactor Administrator

Gentlemen:

This letter refers to the inspection of your activities authorized under NRC License No. R-106 conducted by Mr. W. P. Mortensen of this office on May 14-15, 1979. It also refers to the discussion of our inspection findings held by the inspector with Messrs. J. C. Ringle and A. G. Johnson on May 15, 1979.

The inspection included examination of activities related to physical protection against industrial sabotage and against theft of special nuclear material in accordance with applicable requirements of Title 10, Code of Federal Regulations, Part 73, "Physical Protection of Plants and Materials," your Security Plan, and license conditions pertaining to physical protection as described in the enclosed inspection report. Within these areas, the inspection consisted of selective examinations of procedures and records, interviews with facility personnel and observations by the inspector.

Within the scope of this inspection, no items of noncompliance were observed.

In accordance with Section 2.790(d) of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, documentation of findings of your safeguards and security measures are exempt from public disclosure; therefore, the enclosed inspection report will not be placed in the Public Document Room.

Should you have any questions concerning this letter, we will be glad to discuss them with you.

Sincerely,

*for m D Schuster*  
L. R. Norderhaug, Chief  
Safeguards Branch

336 292

Enclosure:  
IE Inspection Report  
No. 50-243/79-01 (IE-V-307)

①  
7807190145Q