

Appendix A

NOTICE OF VIOLATION

Commonwealth Edison
Company

Docket No. 50-237

Based on the inspection conducted on April 2-30, 1979, it appears that certain of your activities were in noncompliance with NRC requirements, as noted below. This item is an infraction.

Unit 2 Technical Specifications, Section 3.7.A.1 requires the maximum volume in the torus to be 115,655 cubic feet.

Contrary to the above, during a quarterly flow test and subsequent troubleshooting of the HPCI System on January 3, 1979, the technical specification required maximum volume in the torus was exceeded.

7907190497

353 080