



LOCAL PDR

CENTRAL FILES
PDR:HQ
LPDR
TIC
NSIC

PUBLIC SERVICE COMPANY OF COLORADO

P. O. BOX 840 · DENVER, COLORADO 80201

C. K. MILLEN

SENIOR VICE PRESIDENT

May 22, 1979
Fort St. Vrain
Unit No. 1
P-79108

Mr. Karl V. Seyfrit, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Region IV
611 Ryan Plaza Drive
Suite 1000
Arlington, Texas 76012

Subject: I & E Bulletin 79-09

Dear Mr. Seyfrit:

It has been determined that GE Type AK-2 circuit breakers are not installed in safety related systems at the Fort St. Vrain plant.

We plan no further action on this matter.

Very truly yours,

C. K. Millen
Senior Vice President

CKM:FMM:il

cc: U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement,
Division of Reactor Operations Inspection
Washington, D. C. 20555

400 360

(1)

7907190699