

## Simmons, Michelle

---

**From:** Rich Leipertz <richpacific808@gmail.com>  
**Sent:** Thursday, August 15, 2019 12:18 PM  
**To:** Simmons, Michelle  
**Subject:** [External\_Sender] Re: NUCLEAR REGULATORY COMMISSION LICENSE TERMINATION: ADDITIONAL INFORMATION REQUIRED

Michelle,

Here are the termination letter (on my letter head ) and the form 314, Pacific Testing services closed its doors on April 15th for good. we transfered the Troxler gauges to Earth Engineers. They would have had to perform leak test to receive them. Pacific Testing was also inspected by the NRC on March 19th, and they found no violations. I have contacted Earth Engineers to obtain the most current leak tests , with no luck. We have no personnel there anymore and I'm currently living in Pennsylvania. I don't know how much more I can due , to resolve this . See the attached forms. Please let me know what more to do.

Richard Leipertz

**PUBLIC**

- Immediate Release  
 Normal Release

**NON-PUBLIC**

- A.3 Sensitive-Security Related  
 A.7 Sensitive Internal  
 Other: \_\_\_\_\_

Reviewer: MS Date: 8/15/19

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSE/LOCATION INSPECTED:  
Pacific Testing Services, Inc.  
99-1421 Koahe Place, Unit 4  
Aiea, Hawaii 96701

2. NRC/REGIONAL OFFICE  
U.S. Nuclear Regulatory Commission  
Region IV, 1600 East Lamar Blvd  
Arlington, Texas 76011-4511

REPORT NO.: 2019-001

3. DOCKET NUMBER  
030-34643

4. LICENSE NUMBER  
53-29118-01

5. DATE(S) OF INSPECTION  
March 19, 2019

LICENSEE:  
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interview with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy to exercise discretion, were satisfied.

Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 16.11.

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			

NRC INSPECTOR	Alyce Bolger	<i>Alyce Bolger</i>	4/25/2019
BRANCH CHIEF			

**PACIFIC TESTING SERVICES, INC.**

99-1421 Koahu Place, Unit #4  
Aiea, HI 96701

Phone: (808) 487-3503 Fax (808) 488-7053

Website: [www.pacifictestingservices.com](http://www.pacifictestingservices.com) Email: [pacifictesting@hawaii.rr.com](mailto:pacifictesting@hawaii.rr.com)

6/17/2019

DNMS

Nuclear Materials Licensing Branch

U.S. Nuclear Regulatory Commission, Region IV

1600 E Lamar Boulevard Arlington, TX 76011-4511


ATTN: Michelle Hammond

RE: MATERIALS LICENSE TERMINATION

Pacific Testing Services, Inc. (NRC License Number 53-28118-01 )  
no longer has any radioactive equipment in its possession.

We wish to terminate our NRC license.

  
Richard Leipertz  
Manager / *RESIGNED*

NRC FORM 314 (02-2017) 10 CFR 30.260(f), 46 (2017), 72.260(f), and 72.260.99(f)(1)		U.S. NUCLEAR REGULATORY COMMISSION <b>CERTIFICATE OF DISPOSITION          OF MATERIALS</b>		APPROVED BY OMB: NO. 3180-0028 EXPIRES: 02/28/2020
LICENSEE NAME AND ADDRESS PACIFIC TESTING SERVICES, INC. 99-1421 KOAHA R. UNIT #4 AIEA, HI. 96701		LICENSE NUMBER 53-29118-01	DOCKET NUMBER	
		LICENSE EXPIRATION DATE JANUARY 31, 2014		
<b>A. LICENSE STATUS (Check the appropriate box)</b> <input type="checkbox"/> This license has expired. <input checked="" type="checkbox"/> This license has not yet expired; please laminate it.				
<b>B. DISPOSAL OF RADIOACTIVE MATERIAL</b> (Check the appropriate boxes and complete as necessary. If additional space is needed, provide attachments) The licensee, or any individual executing this certificate on behalf of the licensee, certifies that:				
<input type="checkbox"/> 1. No radioactive materials have ever been procured or possessed by the licensee under this license. <input type="checkbox"/> 2. All activities authorized by this license have ceased, and all radioactive materials procured and/or possessed by the licensee under this license number cited above have been disposed of in the following manner:				
<input checked="" type="checkbox"/> a. Transfer of radioactive materials to the licensee listed below: EARTH ENGINEERS, INC. 99-1421 KOAHA R. UNIT #4 AIEA, HI 96701				
<input type="checkbox"/> b. Disposal of radioactive materials:				
<input type="checkbox"/> 1. Directly by the licensee: <input type="checkbox"/> 2. By licensed disposal site: <input type="checkbox"/> 3. By waste contractor:				
<input type="checkbox"/> c. All radioactive materials have been removed such that any remaining residual radioactivity is within the limits of 10 CFR Part 20, Subpart E, and is ALARA.				
<b>C. SURVEYS PERFORMED AND REPORTED</b>				
<input type="checkbox"/> 1. A radiation survey was conducted by the licensee. The survey confirms: TRANSFER CONDUCTED SURVEYS.				
<input type="checkbox"/> a. the absence of licensed radioactive materials <input checked="" type="checkbox"/> b. that any remaining residual radioactivity is within the limits of 10 CFR 20, Subpart E, and is ALARA.				
<input type="checkbox"/> 2. A copy of the radiation survey results:				
<input type="checkbox"/> a. is attached; or <input type="checkbox"/> b. is not attached (Provide explanation); or <input type="checkbox"/> c. was forwarded to NRC on: _____ Date _____				
<input type="checkbox"/> 3. A radiation survey is not required as only sealed sources were ever possessed under this license, and				
<input type="checkbox"/> a. The results of the latest leak test are attached; and/or <input type="checkbox"/> b. No leaking sources have ever been identified.				
The person to be contacted regarding the information provided on this form:				
NAME RICHARD LEIPERTZ	TITLE PRESIDENT	TELEPHONE (Include Area Code) 808-864-4025	E-MAIL ADDRESS RICHARD.LEIPERTZ@GMAIL.COM	
Mail all future correspondence regarding this license to:				
<b>C. CERTIFYING OFFICIAL</b> I CERTIFY UNDER PENALTY OF PERJURY THAT THE FOREGOING IS TRUE AND CORRECT				
PRINTED NAME AND TITLE RICHARD LEIPERTZ	SIGNATURE 	DATE 7-25-2019		
WARNING: FALSE STATEMENTS IN THIS CERTIFICATE MAY BE SUBJECT TO CIVIL AND/OR CRIMINAL PENALTIES. NRC REGULATIONS REQUIRE THAT SUBMISSIONS TO THE NRC BE COMPLETE AND ACCURATE IN ALL MATERIAL RESPECTS. 18 U.S.C. SECTION 1001 MAKES IT A CRIMINAL OFFENSE TO MAKE A WILLFULLY FALSE STATEMENT OR REPRESENTATION TO ANY DEPARTMENT OR AGENCY OF THE UNITED STATES AS TO ANY MATTER WITHIN ITS JURISDICTION.				

On Mon, Aug 12, 2019 at 6:38 PM Simmons, Michelle <Michelle.Simmons@nrc.gov> wrote:

The Nuclear Regulatory Commission (NRC) has completed the technical review of the termination request dated June 17, 2019 for license number 53-29118-01, and additional information is needed.

1. Please complete the attached form, along with supporting documentation (recent leak test results, disposal records, etc.) to the NRC.

Please provide this information by August 22, 2019. Please reference mail control number 612502 in your response. Your response should be on letterhead, sign and dated. You may submit your response by email as a pdf. attachment. If you have any questions, please feel free to send me an e-mail or call me at 817-200-1590. Thank you for your cooperation.

Michelle Simmons



# Gamma Corporation

850 West Hind Drive #214, Honolulu, HI 96821

Phone (808) 373-7009  
FAX (808) 373-7017

## Leak Test Certificate

Facility: Pacific Testing Services

Number: 1725

Department:

Fac ID: PTS

Address: 99-1421 Koaha Place, Unit #4

Aiea

HI

96701

Wipe Date: November 12, 2018

Analysis Date: November 12, 2018

The following sources were leak tested according to the procedures described in NRC License No. 53-23207-01.

All sources used for calibration are traceable to NTIS.

Isotope	Model Number	Serial Number	Activity (MBq)	Results (Bq)
Am-241	Troxler 3440/35072	47-30385	1480	<2
Cs-137	Troxler 3440/35072	77-2179	296	<4

This report must be on file for review by the NRC or state regulatory authorities.

Performed by:

Radiation Safety Officer:



Gamma Corporation

850 West Hind Drive #214, Honolulu, HI 96821

Phone (808) 373-7009

FAX (808) 373-7017

## Leak Test Certificate

Facility: Pacific Testing Services

Number: 1726

Department:

Fac ID: PTS

Address: 99-1421 Koaha Place, Unit #4

Aiea

HI

96701

Wipe Date: December 04, 2018

Analysis Date: December 05, 2018

The following sources were leak tested according to the procedures described in NRC License No. 53-23207-01.

All sources used for calibration are traceable to NTIS.

Isotope	Model Number	Serial Number	Activity (MBq)	Results (Bq)
Am-241	Troxler 3440/21221	47-17704	1480	<2
Cs-137	Troxler 3440/21221	75-2711	296	<4

This report must be on file for review by the NRC or state regulatory authorities.

Performed by:

Radiation Safety Officer:

## Simmons, Michelle

---

**From:** Laura Haigh <Laurah@earth-engineers.com>  
**Sent:** Thursday, August 15, 2019 1:16 PM  
**To:** Simmons, Michelle  
**Subject:** [External\_Sender] leak test reports - Earth Engineers, Inc.  
**Attachments:** EEI leak tests.pdf

Hi Michelle, please see attached

Laura Haigh  
Geotechnical Engineering Associate



**Earth  
Engineers,  
Inc.**

Cell: 808-640-7501  
[laurah@earth-engineers.com](mailto:laurah@earth-engineers.com)  
[www.earth-engineers.com](http://www.earth-engineers.com)

**Hawaii Office:**  
99-1421 Koaha Place, Suite 4  
Aiea, HI 96701  
Phone: 808-208-1454

**Camas Office:**  
2411 S.E. 8<sup>th</sup> Avenue  
Camas, WA 98607  
Office: 360-567-1806  
Fax: 360-253-8624

**Springfield Office:**  
4660 Main Street, Suite 100  
Springfield, OR 97478  
Phone: 541-393-6340  
Fax: 541-393-6385