

**PRECISION PERFORATORS
INCORPORATED**

March 4, 1981

License # 35-19071-01

U. S. Nuclear Regulatory Commission
Attn: Mr. Glen Brown
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76011

Gentlemen:

In reference to the letter we received on Feb. 26, 1981 concerning the safety inspection conducted on Feb. 6, 1981 and the notice of Violations attached to that letter.

On Feb. 18, 1981, we sent a letter requesting an increase from 50 Millicuries to 100 Millicuries of Iridium and Iodine. As of this date, we do not have any on our records.

As of Feb. 9, 1981; records of truck surveys and storage area monitoring are being kept on a regular basis.

Leak test were taken and sent in to Gulf Nuclear on Feb. 11, 1981; as of this date we have not received the results.

If additional information is required, please let me know.

Sincerely,

Mike Reeder

Mike Reeder
President
Precision Perforators, Inc.

MR/br

IN WITNESS WHEREOF, I HAVE SIGNED TO WITNESS THE
THIS 4TH DAY OF MARCH, 1981

MIKE REEDER

My Comm. Day 322

8104200030