

UNITED STATES NUCLEAR REGULATORY COMMISSION REGION III 799 GOSEVELT ROAD GLEN ELLYN, ILLINOIS 60137

MAR 2 3 1981



License No. 24-17210-01

Kirksville College of Osteopathic Medicine ATTN: James R. Stooky, D.O. College Dean 704 West Jefferson Kirksville, MO 63501

Gentlemen:

This refers to the routine safety inspection conducted by Mr. W. P. Reichhold of this office on March 3-4, 1981, of activities authorized by NRC Byproduct Material License No. 24-17210-01 and to the telephone conversation concerning our findings with Paul Willicus, D.O. on March 13, 1981.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

During this inspection, certain of your activities appeared to be in noncompliance with NRC requirements, as described in the enclosed Appendix A, and a written response is required. Kirksville College of Osteopathic Medicine

MAR 2 3 1981

We will gladly discuss any questions you have concerning this inspection.

- 2 -

Sincerely,

D. G. Wiedeman, Acting Chief Radiction Protection Section 1

Enclosure: Appendix A, Notice of Violation

cc: LFMB, ltr only

cc w/encl: Paul Williams, D.O. Radiation Safety Officer Emmett S. Manley, Jr., Ph.D. Chairman, KCOM Biohazards Committee, Associate Dean for Basic Sciences Central Files Reproduction Unit NRC 20b PDR NSIC

RIII RIII Wiedeman Reichhold/np

Keichhold/1 3/17/81