



AMPHENOL

AMPHENOL SAMS DIVISION

9201 Independence Ave. • Chatsworth, Calif., 91311 • (213) 341-0710 • TWX 910-494-1211

March 30, 1979

United States Nuclear
Regulatory Commission
Region IV
611 Ryan Plaza Drive
Suite 1000
Arlington, Texas 76011

Attn: Mr. Uldis Potapovs,
Chief Vendor Inspector Branch

Subj: NRC Report No. 99900116/79-01,
Program No. 51300

Quality Assurance has received subject report and is now in the process of reviewing and interpreting same.

The writer received subject report March 30, 1979. This office will take the necessary actions to comply with the report. However, it may take more than 30 days from this date. Therefore, the writer is requesting an additional 30 days to comply.

Your cooperation in this matter will be appreciated.

Yours truly,
BUNKER RAMO CORPORATION

Howard D. Wright
Howard D. Wright
Quality Assurance Manager
Amphenol North America
SAMS Operation

HDW/met

~~369 212~~

7907130 251

459 094