

Bunker Ramo Corporation
Docket No. 99900116/79-01

NOTICE OF DEVIATION

Based on the results of an NRC inspection conducted on February 20-23, 1979, it appeared that certain of your activities were not conducted in full compliance with NRC requirements as indicated below:

Criterion XVIII of Appendix B to 10 CFR 50 states in part, "... audits shall be performed in accordance with the written procedures or check lists by appropriately trained personnel"

ASME Code Article NA-4000 Quality Assurance, Section NA-4132 states in part, "The program shall provide for indoctrination and training of personnel performing activities affecting quality as necessary to assure that suitable proficiency is achieved and maintained"

QA Manual paragraph 1.5.2 and 1.5.3 states in part, "Records of employee training shall be maintained by . . . the Quality Assurance Department . . . the Manager of Quality Assurance shall be responsible for assuring that personnel performing functions relating to Quality Assurance are properly qualified through training programs"

Contrary to the above, although Quality Assurance Engineers (Auditors), performing functions related to Quality Assurance had received training, records of the training were not maintained by the Quality Assurance Department.

~~369 215~~

459 087

7907130370