



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION IV
611 RYAN PLAZA DRIVE, SUITE 1000
ARLINGTON, TEXAS 76012

TEBA
TEBA

Docket No. 50-298

May 31, 1979

Nebraska Public Power District
ATTN: J. M. Pilant, Director
Licensing and Quality Assurance
P. O. Box 499
Columbus, Nebraska 68601

Gentlemen:

This refers to the inspection conducted by Blaine Murray of this office during April 30 - May 4, 1979, of activities authorized by NRC Operating License No. DPR-46 and to the discussion of the inspection findings held by Mr. Murray with Mr. L. C. Lessor at the conclusion of the inspection on May 4, 1979.

Areas examined during the inspection and our findings are discussed in the enclosed inspection report. Within these areas, the inspection consisted of selective examination of procedures and representative records, interviews with personnel, and observations by the inspector.

Within the scope of this inspection, no items of noncompliance were disclosed.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC's Public Document Room. If this report contains any information that you believe to be proprietary, it is necessary that you make a written application within 20 days to this office to withhold such information from public disclosure. Any such application must include a full statement of the reasons on the basis of which it is claimed that the information is proprietary, and should be prepared so that proprietary information identified in the application is contained in a separate part of the document. If we do not hear from you in this regard within the specified period, the report will be placed in the Public Document Room.

508 353

510 002

7907190038

Q

Nebraska Public Power District

2

May 31, 1979

Should you have any questions concerning this letter, we will be pleased to discuss them with you.

Sincerely,



G. L. Madsen, Chief
Reactor Operations and
Nuclear Support Branch

Enclosure:

IE Inspection Report No. 50-298/79-08

cc: I. C. Lessor
P. O. Box 98
Brownville, Nebraska 68321

510 003