

Appendix A

NOTICE OF VIOLATION

American Cyanamid Company

License No. SUB-1320

Based on the inspection conducted on March 12 and May 17, 1979, it appears that certain of your activities were in noncompliance with NRC requirements, as noted below. Item 1 is an infraction and Item 2 is a deficiency.

1. Condition 13 of your license requires that licensed material be possessed and used in accordance with the statements, representations and procedures contained in your letter dated August 10, 1977.

Contrary to the requirements of your letter, the last calibration of your survey instruments prior to the inspection conducted on March 12, 1979 was April 24, 1978, a period in excess of six months.

2. 10 CFR 19.11(a) and (b) require that current copies of Part 19, Part 20, license conditions, documents incorporated into the license, license amendments, and operating procedures be posted, or that a notice describing these documents and where they may be examined, be posted. 10 CFR 19.11(d) requires that these documents or notices appear in a sufficient number of places to permit individuals engaged in licensed activities to observe them.

Contrary to this requirement, on March 12, 1979, neither the documents nor the notices were posted.

7907190865

485 100