



MATERIAL TRANSMITTED HEREWITH
CONTAINS SENSITIVE INFORMATION
NUCLEAR REGULATORY COMMISSION

REGION II
101 MARIETTA STREET, N.W.
ATLANTA, GEORGIA 30303

MAY 14 1979

Report No. 70-1151/79-6

Licensee: Westinghouse Electric Corporation
Nuclear Fuel Division
Columbia, South Carolina 29205

Docket No. 70-1151

License No. SNM-1107

Inspectors:

D. W. Jones

G. A. Todd

Approved by:

F. P. Gillespie, Section Chief, Safeguards Branch

5/11/79

Date Signed

5/11/79

Date Signed

5/11/79

Date Signed

SUMMARY

Inspection on April 24-27, 1979.

Areas Inspected

This routine unannounced inspection involved 42 inspector-hours on site in the areas of facility organization, storage and internal control, and shipping and receiving.

Results

Of the three areas inspected, no apparent items of noncompliance or deviations were identified in two areas; two apparent items of noncompliance were found in one area (Deficiency - Failure to complete NRC-741 Forms in accordance with printed instructions (79-06-01); Deficiency - Failure to reconcile statistically significant shipper-receiver differences (79-06-02)), one apparent deviation was found in one area (failure to use 19 strand wire for tamper-safing seals (79-06-03)).

S-F2 79 - 60P
Copy 6 of _____ Copies
This copy is to be retained without specific approval of the II

480-290

MATERIAL TRANSMITTED HEREWITH
CONTAINS SENSITIVE INFORMATION

7907300070


Westinghouse Electric Corporation -2-

MAY 14 1979

your comments including a description of corrective actions that have been or will be taken, corrective actions which will be taken to avoid further deviations, and the date corrective actions were or will be completed. Details of activities involving safeguards or security measures are exempt from disclosure in accordance with 10 CFR 2.790(d). Therefore, your response should be incorporated in a separate paper and referenced in your reply.

Should you have any questions concerning this letter, we will be glad to discuss them with you.

Sincerely,


W. B. Kenna, Chief
Safeguards Branch

Enclosures:

1. Appendix A, Notice of Violation
(Exempt from Disclosure)
2. Appendix B, Notice of Deviation
(Exempt from Disclosure)
3. Inspection Report No. 70-1151/79-6
(Exempt from Disclosure)
4. Inspection Summary
(Not Exempt)

480-291