PAK



## Houston ompany

Electric Tower P.O. Box 1700 Houston, Texas 77001

May 21, 1979 SFN: V-0540 ST-HL-AF-342

Director, Region IV Office of Inspection and Enforcement 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76102

Dear Sir:

South Texas Project Units 1 & 2 Docket Nos. STN 50-498, STN 50-499 IE Bulletin No. 79-04

Bulletin No. 79-04, received April 2, 1979, has been reviewed by Houston Lighting & Power Company. Investigation indicates that swing check valves manufactured by Velan Manufacturing Corporation are not being utilized in the South Texas Project, and therefore no action is necessary.

If you have any questions, please contact us.

Very truly yours,

E. A. Turner Vice President

Power Plant Construction & Technical Services

PLW:bf

cc: Director, NRC Office of Inspection & Enforcement

C. Thrash (Baker & Botts)

R. Gordon Gooch (Baker & Botts)

J. R. Newman (Lowenstein, Newman, Reis, Axelrad & Toll)

D. G. Barker

A. J. Granger

R. A. Frazar