DAIRYLAND POWER COOPERATIVE

La Crosse, Odisconsin

54601

May 30, 1979

In reply, please refer to LAC-6321

DOCKET NO. 50-409

Mr. James G. Keppler
Regional Director
U. S. Nuclear Regulatory Commission
Directorate of Regulatory Operations
Region III
799 Roosevelt Road
Glen Ellyn, Illinois 60137

SUBJECT: DAIRYLAND POWER COOPERATIVE

LA CROSSE BOILING WATER REACTOR (LACBUR)

PROVISIONAL OPERATING LICENSE NO. DPR-45

IE BULLETIN NO. 78-12B - ATYPICAL WELD

MATERIAL IN REACTOR PRESSURE VESSEL WELDS

Reference: (1) NRC Letter, Keppler to Linder, dated March 19, 1979.

(2) DPC Letter, LAC-6095, Linder to Keppler,

dated January 30, 1979.

(3) NRC Letter, Keppler to Linder, dated November 24, 1978.

(4) DPC Letter, LAC-6012, Linder to Keppler,

dated November 27, 1978.

(5) NRC Letter, Keppler to Madgett, dated September 29, 1978.

Dear Mr. Keppler:

In response to IE Bulletin 78-12B enclosed with Reference 1, in which the response requirements for IE Bulletin No. 78-12 and IE Bulletin No. 78-12A were modified, the following information is submitted in addition to information previously submitted by References 2 and 4.

No generic report for the La Crosse Boiling Water Reactor vessel will be submitted by Allis-Chalmers since the LACBWR reactor vessel was the last reactor vessel manufactured by Allis-Chalmers, and LACBWR has all existing relevant records. References 2 and 4 contain all available information requested by TE Bulletin No. 78-12 (Reference 5).

- 1 -

469 335

01 1979

LAC-6321 May 30, 1979

Mr. James G. Keppler Regional Director

Authorization for this response to be submitted on May 30, 1979 was granted by Mr. Ken Ridgway to Mr. Richard Shimshak on May 29, 1979.

If there are any questions concerning this response, please contact us.

Very truly yours,

DAIRYLAND POWER COOPERATIVE

Frank Synder /sf
Frank Linder, General Manager

FL:RES:af