

Telephone 617 366-9011

TWX

710-390-0739

B. 4. 2. 1

WYR 79-77

YANKEE ATOMIC ELECTRIC COMPANY



20 Turnpike Road Westborough, Massachusetts 01581

July 7, 1979

United States Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, Pennsylvania 19406

Attention: Mr. Boyce H. Grier, Director

References: (1) License No. DPR-3 (Docket No. 50-29)
(2) USNRC, Region 1 letter, dated May 22, 1979
IE Bulletin 79-11

Dear Sir:

Subject: Faulty Overcurrent Trip Devices on Westinghouse DB Circuit Breakers

Reference (2) required Yankee Rowe to determine if Westinghouse type DB circuit breakers are installed in safety-related Class 1E circuits or in spares.

Yankee Rowe has determined that the subject circuit breakers are not used in safety-related Class 1E circuits.

We plan no further action on IE Bulletin 79-11.

We trust that you find this information satisfactory; however, if you require any additional information, please contact us.

Very truly yours,

YANKEE ATOMIC ELECTRIC COMPANY

Robert H. Groce
Licensing Engineer

PRJ/jgh

539 321

7908 070673