

PGE

August 3, 1979


Director of Nuclear Reactor Regulation
ATTN: Mr. A. Schwencer, Chief
Operating Reactors Branch #1
Division of Operating Reactors
U.S. Nuclear Regulatory Commission
Washington, D. C. 20555

Dear Sir:

Specification 4.2.3.1 of Appendix B to the Trojan Operating License (FOL), NPF-1, outlines procedures to be followed if milk samples cannot be obtained as specified in Table 4-2 of Appendix B. Milk samples are currently required by Table 4-2 to be taken monthly from the Palmer Dairy, listed as Location 17. This dairy is no longer operational and, from all indications, will not resume operations in the foreseeable future. In accordance with Sections 4.2.3.1 and 5.5.3(b) of Appendix B of the Trojan FOL, NPF-1, you are hereby advised that milk samples are no longer being taken from this sampling location.

Although no suitable alternative to this site is currently available, PGE is maintaining a continual awareness of milk-producing animals in the Trojan environs. Should the Palmer Dairy again become operational or should another suitable milk sampling site develop, PGE will initiate a sampling program from these locations as soon as possible. License Change Application 50, submitted to your office on March 15, 1979, corrects this discrepancy in our environmental radiation monitoring program. Should you have questions or concerns, please do not hesitate to contact me.

Sincerely,


C. Goodwin, Jr.
Assistant Vice President
Thermal Plant Operations and
Maintenance

CG/GAZ/4sbl0A7

c: Mr. R. H. Engelken, Director
Nuclear Regulatory Commission
Region V I&E

Mr. Lynn Frank, Director
State of Oregon
Department of Energy

504 340

7908080 467

Cook
S/P