

Babcock & Wilcox

Power Generation Group

7735 Old Georgetown Road, Bethesda, Md. 20014

Telephone: (301) 951-0202

May 8, 1979

RECEIVED  
ADVISORY COMMITTEE ON  
REACTOR SAFEGUARDS U.S. N.R.C

MAY 11 1979


AM PM  
7 8 9 10 11 12 1 2 3 4 5 6

Dr. R. J. Mattson, Director  
Division of Systems Safety  
Office of Nuclear Reactor Regulation  
US Nuclear Regulatory Commission  
Washington, DC 20555

Dear Dr. Mattson:

The B&W report, "Evaluation of Transient Behavior and Small Reactor Coolant System Breaks in the 177 Fuel Assembly Plant - May 7, 1979" submitted to you by my letter dated May 7, 1979 inadvertently had information missing in Appendix 1. Therefore, I am transmitting to you a revised Appendix 1, "Natural Circulation in B&W Operating Plants (Revision 1)." As you will note, information regarding an event which occurred at ANO-1 has been added to this Appendix. In order to expedite your efforts, a complete revised Appendix 1 is forwarded to you. Please replace the previously submitted Appendix 1 with the revised version.

Very truly yours,



James H. Taylor  
Manager, Licensing  
Nuclear Power Generation Division

JHT:bm

6002  
5/11

7908090587\*