



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION I  
631 PARK AVENUE  
KING OF PRUSSIA, PENNSYLVANIA 19406

For  
CY

Docket No. 30-6182

JUN 13 1979

Pullman Incorporated  
Pullman Power Products Division  
ATTN: Mr. E. Baker  
Plant Manager  
Reach Road  
Williamsport, Pennsylvania 17701

Gentlemen:

Subject: Inspection 79-01

This refers to the inspection conducted by Mr. E. Epstein of this office on May 15, 1979 of activities authorized by NRC License No. 37-08042-01 and to the discussions of our findings held by Mr. Epstein with yourself at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, measurements made by the inspector, and observations by the inspector.

In addition, our inspector made leak tests on your sealed sources. These tests were analyzed in our Regional Office Laboratory in King of Prussia, Pennsylvania. The basic purpose of these independent measurements was to verify your capability of analyzing leak test samples. The results of our analysis were in agreement with your results and indicate levels below the limits specified in your license.

Within the scope of this inspection, no items of noncompliance were observed.

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter will be placed in the Public Document Room.

7908130 094

551076


Pullman Incorporated

- 2 -

JUN 13 1979

No reply to this letter is required; however, should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

A handwritten signature in cursive script, appearing to read "Robert O. McClintock".

Robert O. McClintock, Chief  
Materials Radiological Protection  
Section

551077