

MC

DAIRYLAND POWER COOPERATIVE

La Crosse, Wisconsin

54601

July 11, 1979

In reply, please
refer to LAC-6403

DOCKET NO. 50-409

Mr. James G. Keppler, Regional Director
U. S. Nuclear Regulatory Commission
Directorate of Regulatory Operations
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

SUBJECT: DAIRYLAND POWER COOPERATIVE
LA CROSSE BOILING WATER REACTOR (LACBWR)
PROVISIONAL OPERATING LICENSE NO. DPR-45
SwRI SPECIAL REPORT NO. 17-5627, THE SIXTH
MECHANIZED ULTRASONIC INVESTIGATION OF A
LAMINAR INDICATION IN THE PLATE OF THE
LA CROSSE BOILING WATER REACTOR PRESSURE VESSEL

REFERENCE: (1) LACBWR Technical Specifications
Section 3.9.4.1.b.

Dear Mr. Keppler:

For your information, enclosed are three (3) copies each of the
subject report.

This report was prepared as a result of the continuing Inservice
Examination Program of the La Crosse Boiling Water Reactor and
associated components.

If there are any questions concerning this report, please
contact us.

Very truly yours,

DAIRYLAND POWER COOPERATIVE

Frank Linder

Frank Linder, General Manager

FL:HAT:abs

Enclosure

JUL 10 1979

7908130661

653 357

Mr. James G. Keppler, Reg. Dir.
USNRC-Region III

LAC-6403
July 11, 1979

CC: Mr. John J. Duffy
Chief Boiler Inspector
Safety and Building Division
Post Office Box 2209
Madison, WI 53701 (w/o encl.)

Paul G. Vaher
Factory Mutual Engineering
3333 North Mayfair Road
Milwaukee, WI 53222 (w/encl.)

Mr. Harold Jorgensen
Authorized Inspector
Factory Mutual
2433 North Mayfair Road
Milwaukee, WI 53226 (w/encl.)

Mr. Virgil Kanable
Dept. of Industry, Labor & Human Relations
Industrial Safety & Buildings Division
P. O. Box 2209
Madison, WI 53701 (w/o encl.)

C. E. Lautzenheizer
Southwest Research Institute
P. O. Drawer 28510
8500 Culebra Road
San Antonio, TX 78284 (w/o encl.)