



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION III  
799 ROOSEVELT ROAD  
GLEN ELLYN, ILLINOIS 60137

July 17, 1979

Mr. L. E. Roe, Vice President,  
Facilities Development  
Toledo Edison Company  
Edison Plaza  
300 Madison Avenue  
Toledo, Ohio 43652

Dear Mr. Roe:

This letter confirms the resolution of the Fire Prevention Program issues for Davis-Besse Nuclear Power Station, Unit No. 1, as discussed with you on July 5, 1979, by members of my staff. The issues involved are briefly described in the attachment to this letter. The details are included in Inspection Report No. 50-346/79-15.

We would be happy to discuss this matter further with you if you so desire.

Sincerely,

*James G. Keppler*  
James G. Keppler  
Director

Enclosure: Fire Prevention  
Program Issues

cc w/encl:

T. D. Murray, Station  
Superintendent

Central Files

Reproduction Unit NRC 20b

PDR

Local PDR

NSIC

TIC

Harold W. Kohn, Power  
Siting Commission

647 280

7908140092

ISSUE

RESOLUTION

AD 1828.20 needs to list the requirement to perform at least one drill per year on a "Back Shift" for each fire brigade.

Commitment to make procedure changes by October 25, 1979.

AD 1828.20 needs to list the requirement to perform a sufficient number of unannounced drills.

Commitment to make procedure changes by October 25, 1979.

AD 1810.01 needs to provide for additional portable suppression equipment for transient fire loads.

Commitment to make procedure changes by October 25, 1979.

AD 1810.01 needs to list the restrictions prohibiting smoking in safety-related areas.

Commitment to make procedure changes by October 25, 1979.

NOTE: The above resolutions are consistent with the facility license to have the Fire Protection Program completely implemented by the first refueling.

447 281

ISSUE

RESOLUTION

Failure to review and approve fire protection program implementation procedures. (Pre-plans)

Commitment to review and approve all pre-plans distributed by October 25, 1979.

Failure to establish, implement and maintain adequate procedures covering fire protection program implementation.

Commitment to make identified procedure changes to administrative controls by October 25, 1979.

Fire emergency procedure EP1202.35 needs to be changed to guide Control Room personnel to the fire pre-plans in event of fire.

Commitment to make procedure changes by July 31, 1979.

Service water emergency procedure EP1202.19 needs to be changed to include a valve line-up check sheet and return to normal.

Commitment to make procedure changes by July 15, 1979.

All fire brigade members need to be qualified on respiratory training.

Commitment to qualify all fire brigade members by October 25, 1979.

AD 1810.00 needs to list the physical examination requirements for each fire brigade member.

Commitment to make procedure changes by October 25, 1979.

AD 1810.00 needs to list the minimum eligibility requirements of a fire protection engineer position.

Commitment to make procedure changes by October 25, 1979

AD 1828.20 needs to provide for classroom instruction program to be repeated over a two year period.

Commitment to make procedure changes by October 25, 1979.

AD 1828.20 needs to provide for practice sessions under strenuous conditions

Commitment to make procedure changes by October 25, 1979.

647 282