



**Commonwealth Edison**  
Zion Generating Station  
Shiloh Blvd. & Lake Michigan  
Zion, Illinois 60099  
Telephone 312/746-2084

July 30 , 1979

Mr. James G. Keppler  
Regional Director  
Directorate of Regulatory Operations  
Region III  
U.S. Nuclear Regulatory Commission  
Glen Ellyn, Illinois 60137

Reference: Zion Generating Station  
Docket No. 50-295/DPR-39  
Technical Specification, Section 3.3.2.F.3

Dear Mr. Keppler:

Enclosed please find Reportable Occurrence Report No. 50-295/79-44 for Zion Generating Station, concerning a manual safety injection on Unit 1. This occurrence was reported to J. Kohler, Region III, verbally on 6/8/79.

This report is submitted to you in accordance with the requirements of the Technical Specifications, Section 3.3.2.F.3, which requires an analysis to be submitted within 90 days.

Very truly yours,

*N. E. Wandke*  
for N. E. Wandke  
Superintendent  
Zion Station

Enclosure: Reportable Occurrence Report No. 50-295/79-44

*A002  
S 1/1*

AUG 3 1979

*650 103*

7908140780