

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

REPORT SOURCE L 6 0 5 0 - 0 3 2 4 7 0 7 1 7 9 8 0 8 1 0 7 9 9

60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)NRC USE ONLY

PHONE: 919-457-9521

Facility: BSEP Unit No. 2

Event Date: 7-14-79

Both HPCI units and the other RCIC unit were inspected with no problems found. This is considered an isolated event with no further action required.