



ARKANSAS POWER & LIGHT COMPANY  
POST OFFICE BOX 551 LITTLE ROCK, ARKANSAS 72203 (501) 371-4000

July 9, 1979

2-079-3

Mr. K. V. Seyfrit, Director  
Office of Inspection & Enforcement  
U. S. Nuclear Regulatory Comm.  
Region IV  
611 Ryan Plaza Drive, Suite 1000  
Arlington, TX. 76011

Subject: Arkansas Nuclear One - Unit 2  
Docket No. 50-368  
License No. NPF-6  
Reportable Occurrence Report  
Nos. 50-368/79-44 and 50-368/  
79-45  
(File: 2-0520)

Gentlemen:

In accordance with Arkansas Nuclear One - Unit 2 Technical Specification 6.9.1.9, we have attached the subject reports concerning a containment isolation valve being inoperable for less than two (2) hours (50-368/79-44) and the number of operable Core Protection Calculator (CPC) channels being one less than the total number of channels (50-368/79-45).

Very truly yours,

*David C. Trimble*

David C. Trimble  
Manager, Licensing

DCT:gp

Attachment

cc: Mr. Victor Stello, Jr., Director  
Office of Inspection and  
Enforcement  
U. S. Nuclear Regulatory Comm.  
Washington, DC. 20555

Mr. W. D. Johnson  
U. S. Nuclear Regulatory Comm.  
P. O. Box 2090  
Russellville, AR. 72801

Mr. Norman M. Haller, Director  
Office of Management and  
Program Analysis  
U. S. Nuclear Regulatory Comm.  
Washington, DC. 20555

339 028

3

7907160 283