

aryland hipbuilding & rydock empany

SUBSIDIARY OF FRUEHAUF CORPORATION

P. O. BOX 537 · BALTIMORE, MARYLAND 21203

(AREA CODE 301) 355-0500

May 30, 1979

United States
Nuclear Regulatory Commission
Transportation Branch
Division of Fuel Cycle and Material Safety
Washington, D.C. 20555

Subject: Quality Assurance Requirements for Transporting Radioactive Material

Reference: (A) Letter of April 27, 1979 FCTR:RHO 71-0031
(B) N.R.C. Regulations 10 CFR Part 71

(C) State of Maryland Radioactive Material License No. MD-07-023-01

(1) 49NDT15 Administrative, Operating and Emergency Instructions to Quality Control Personnel for Handling Iridium Radioisotope

Gentlemen:

Enclosure:

In reply to jour letter, Reference (A), seven (7) copies of Enclosure (1) are being submitted to conform with the requirements of Reference (B), and are herewith forwarded for your approval and/or comments.

Your reply will be greatly appreciated.

Wilton K. Carter, Jr.

Superintendent of Quality Control

WKC/pjs Fnclosure DOCKTIED USNRC

JUN 1 1979 > SAME STOTION

TO STOTION

342 322

3: 4100612062