



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION III  
799 ROOSEVELT ROAD  
GLEN ELLYN, ILLINOIS 60137

~~CENTRAL FILES~~

TEVA

JUL 23 1979

Docket No. 50-409

Dairyland Power Cooperative  
ATTN: Mr. F. W. Linder  
General Manager  
2615 East Avenue - South  
LaCrosse, WI 54601

Gentlemen:

This refers to the inspection conducted by Mr. T. J. Madeda and Ms. J. C. Scheffer of this office, on June 21 and 22, 1979, of activities at LaCrosse Boiling Water Reactor (LACBWR) authorized by NRC License No. DPR-45 and to the discussion of our findings with Mr. R. Shimshak and other members of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel. Region III inspectors also followed up on its Immediate Action Letter to the licensee dated March 23, 1979.

During this inspection, certain of your activities appeared to be in noncompliance with NRC requirements, as described in the enclosed Appendix A. The inspection showed that action had been taken to correct item 1 and to prevent recurrence. Consequently, no reply to this item is required and we have no further questions regarding this item at this time. You are requested to provide a written response concerning the remaining item.

This notice is sent to you pursuant to the provisions of Section 2.201 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations. Section 2.201 requires you to submit to this office within twenty days of your receipt of this notice a written statement or explanation in reply, including for each item of noncompliance: (1) corrective action taken and the results achieved; (2) corrective action to be taken to avoid further noncompliance; and (3) the date when full compliance will be achieved.

ATTACHMENT CONTAINS  
10 CFR 2.790 (d) INFORMATION

402 247

③  
7908010002

JUL 23 1979

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

J. A. Hind, Chief  
Safeguards Branch

Enclosures:

- 1. Appendix A, Notice of Violation
- 2. IX Inspection Report  
No. 50-409/79-14  
(Part 2.790(d) Information)

cc w/encls:

Mr. R. E. Shimbak, Plant  
Superintendent  
Central Files  
Reproduction Unit NRC 20b

cc w/o encls:

FDR  
Local FDR

**POOR ORIGINAL**

ATTACHMENT CONTAINS  
10 CFR 2.790 (d) INFORMATION

402 248

OFFICE	RIII	RIII	RIII	RIII	RIII
SURNAME	Madoda/gc	Scheffer	Donahue	Hind	Ridgway
DATE	7/17/79				