

U.S. NUCLEAR REGULATORY COMMISSION
OFFICE OF INSPECTION AND ENFORCEMENT

REGION III

Report No. 50-409/79-14

Docket No. 50-409 License No. DPR-45 Safeguards Group No. IV

Licensee: Dairyland Power Cooperative
2615 East Avenue - South
LaCrosse, WI 54601

Facility Name: LaCrosse Boiling Water Reactor (LACBWR)

Inspection At: Genoa, Wisconsin

Inspection Conducted: June 21-22, 1979

Date of Last Physical Security Inspection Visit: March 12-16, 1979

Type of Inspection: Immediate Action Letter Follow-up

Inspectors: *Terry J. Madala*
T. J. Madala
Physical Security Specialist
J. C. Schefter
J. C. Schefter
Physical Security Specialist

7/18/79
(Date)

7/15/79
(Date)

Approved By: *J. F. Donahue*
J. A. Hind, Chief
Safeguards Branch

7/15/79
(Date)

Inspection Summary

Inspection on June 21 and 22, 1979 (Report No. 50-409/79-14)

Areas Inspected: Included follow-up on items identified in Immediate Action Letter of March 23, 1979; follow-up on items identified during the previous physical security inspection; review of Physical Barriers (Protected Area); Physical Barriers (Vital Area); Access Control (Vital Area), and Locks, Keys and Combinations. The inspection involved 19 inspector-hours onsite by two NRC inspectors. The inspection was begun during the day shift period and 2 inspection-hours were accomplished during off-shift periods.

Results: The licensee was found to be in compliance with NRC requirements within the areas inspected except for the following 2 items:

1. Physical Barriers (Vital Area) - A vital area portal was not maintained properly. (Infraction)
2. Locks, Keys and Combinations - The licensee utilized improper locking mechanisms. (Deficiency)

(Details: Part 2.790(d) Information)

S-F3-79-124
Copy 3 of 7 copies
5 Pages.

THIS DOCUMENT IS NOT TO BE
REPRODUCED WITHOUT SPECIFIC
APPROVAL OF BIII

402

249

7908010009