

UNITED STATES NUCLEAR REGULATORY COMMISSION REGION III 799 ROOSEVELT RGAD GLEN ELLYN, ILLINOIS 60137

JUN 2 1 1979

License No. 12-02370-01

Superior Industrial X-ray Company ATTN: Mr. John J. Turner President 126th Street and Homan Avenue Blue Island, IL 60406

Gentleme...:

This refers to the telephone contacts on May 14 and 15, 1979, between you and W. H. Schultz of this office regarding the failure of Superior Industrial X-ray Company personnel to maintain constant surveillance over a radiographic exposure device containing a iridium 192 sealed source which was in an unrestricted area.

Specifically, one of your radiography trucks was at the Fermi Laboratory in Warrenville, Illinois, on May 14, 1979, at which time a radiographic exposure device was placed on the tail gate of the truck awaiting a survey by Fermi health physics personnel. When the health physicist arrived to make the survey he noted the exposure device was not under the surveillance of a radiographer who was in the cab of the truck. The health physicist then took possession of the exposure device and after several hours returned it to the radiographer.

It should be noted that failure to maintain constant surveillance and immediate control of licensed materials in an unrestricted area is not in accordance with the requirements of 10 CFR 20.207.

This matter will be reviewed during the next scheduled inspection.

We will gladly discuss any questions you have concerning this matter.

Sincerely,

1BDans

A. B. Davis, Chief Fuel Facility and Materials Safety Branch

cc: Central Files Reproduction Unit NRC 20b PDR Local PDR

423 168

7908020364