

NORTHWESTERN UNIVERSITY  
EVANSTON - CHICAGO

OFFICE OF RESEARCH SAFETY

B - 106 WARD BUILDING  
303 EAST CHICAGO AVENUE  
CHICAGO, ILLINOIS 60611

March 3, 1981

Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137


re: 12-00382-03  
Leaking Sealed Sources

In September, 1980, I notified you that we have placed a 5 millicurie (12/78) cadmium-109 sealed source in storage until a decision could be made with regard to its repair or disposal.

The manufacturer was contacted and the source returned to them in October, 1980, where it was repaired. It was returned to the University in November, 1980, and is back in use.

This letter is a follow-up to our original correspondence.

Sincerely,



David R. Miller, Ph.D.  
Director

m

c Dr. Lewis  
Dr. Rachmeler  
Mr. Scislowicz

8103250 677

MAR 5 1981