

Appendix A

NOTICE OF VIOLATION

Consumers Power Company

Docket No. 50-329

Docket No. 50-330

Based on the results of an NRC inspection conducted on April 2-30, 1979, it appears that certain of your activities were in noncompliance with NRC requirements as noted below.

These items are considered infractions.

10 CFR 50, Appendix B, Criterion V, states, in part, "activities affecting quality shall be prescribed by documented instructions, procedure or drawings, . . . , and shall be accomplished in accordance with instructions, procedure or drawings.

CBI Hydrostatic Test Procedure HP-71701 Step 7.3 states in part, "Inspect all joints and connections."

Contrary to the above, it was determined on April 2, 1979 that all joints and connections on Incore Instrument Tank No. 2T-87 could not have been physically examined using the technique employed because of confining geometry.

7908150620

692312