

DUPLICATE ORIGINAL CONTROL BUSINESS



THE MILLSTONE LIGHT AND POWER COMPANY  
THE MILLSTONE UNIT OPERATING COMPANY  
MILLSTONE UNIT OPERATING COMPANY  
MILLSTONE UNIT OPERATING COMPANY  
MILLSTONE UNIT OPERATING COMPANY  
MILLSTONE UNIT OPERATING COMPANY  
MILLSTONE UNIT OPERATING COMPANY  
MILLSTONE UNIT OPERATING COMPANY

P.O. BOX 270  
HARTFORD, CONNECTICUT 06101  
(203) 666-6911

Mr. Boyce H. Grier  
Director, Region I  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, Pennsylvania 19406

August 10, 1979  
MP-1-1278

Reference: Provisional License DPR-21  
Docket Number 50-245  
Reportable Occurrence RO-79-21/3L

Dear Mr. Grier:

This letter forwards the Licensee Event Report for Reportable Occurrence RO-79-21/3L required to be submitted within 30 days pursuant to the requirements of the Millstone Unit 1 Technical Specifications, Section 6.9.1.9. An additional three copies of the report are enclosed.

Yours truly,

J. F. Opeka  
Station Superintendent  
Millstone Nuclear Power Station

JFO:RHY:cp

Attachment: (LER RE-79-21/3L)

cc: Director, Office of Inspection and Enforcement, Washington, D.C. (30)  
Director, Office of Management Information and Program Control,  
Washington, D.C. (3)

POOR ORIGINAL

759219

7908160471