	ON FINDINGS AND L	2. REGIONAL OFFIC	£
X-RAY INDUSTRIOS INC 18711 JOIN R. STROBT DOTROIT MICH 48203		U. S. Nuclear Regulatory Commission Office of Inspection and Enforcement	
DOJRDIT MICH	48203	Region III 799 Roosevelt	Pood
		Glen Ellyn, Il	
DOCKET NUMBER(S)	4. LICENSE NUMBER		B. DATE OF INSPECTION
3004837	21-05-17	2-01	7/2/79
6. INSPECTION FINDINGS The inspection was an examination of the act Commission's rules and regulations and the co sentative records, interviews with personnel, and	nditions of your license. Th	he inspection consisted of s	selective examinations of procedures and repre-
No items of noncompliance or uns	afe conditions were fou	ind.	
The following items of noncompliance re-			
A. Rooms or areas were not prope	rly posted to indicate th	ne presence of a RADIA	ATION AREA. 10 CFR 20.203(b) or 34.4
B. Rooms or areas were not prope 10 CFR 20.203(c) (1) or 34.42	rly posted to indicate th	ne presence of a HIGH I	RADIATION AREA.
C. Rooms or areas were not prope 10 CFR 20.203(d)	rly posted to indicate th	ne presence of an AIRB	ORNE RADIOACTIVITY AREA.
D. Rooms or areas were not prope	rly posted to indicate th	ne presence of RADIOA	CTIVE MATERIAL. 10 CFR 20.203(e)
E. Containers were not properly la 10 CFR 20.203(f) (1) or (f) (2)	beled to indicate the pr	esence of RADIOACTI	VE MATERIAL.
F. A current copy of 10 CFR 20, a made available. 10 CFR 20.206	a copy of the license, or (b)	a copy of the operating	g procedures was not properly posted or
G. FormNRC-3 was not properly p	posted. 10 CFR 20.206	(c)	
H. Records of the radiation exposu	ire of individuals were r	iot properly maintained	l. 10 CFR 20.401(a) or 34.33(b)
I. Records of surveys or disposals	were not properly main	tained. 10 CFR 20.401	(b) or 34.43(d)
J. Records of receipt, transfer, dis 10 CFR 30.51, 40.61 or 70.51	posal, export or invento	ory of licensed material	were not properly maintained.
K. Records of leak tests were not r	naintained as prescribed	in your license, or 10 (	CFR 34.25(c)
L. Records of inventories were not	maintained. 10 CFR 3-	4.26	
M. Utilization logs were not mainta	ined. 10 CFR 34.27		
N. Records of radiation survey inst	rument calibration were	e not maintained. 10 CH	FR 34.24
O. Records of teletherapy electrica	l interlock tests were no	ot maintained as prescri	bed in your license.
P. Other		7	0
	Ster	Ind The	ty
• The NRC Inspector has explained a	nd I understand the it	ems of noncompliance	listed above. The items of
noncompliance will be corrected wit	hin the next 30 days.		762102

7908240 /33