

License No. SUB-1010

NOTICE OF VIOLATION

Based on the results of the NRC inspection conducted on May 21-24, 1979, certain activities appear to be in noncompliance with NRC regulations as indicated below:

Contrary to 10 CFR 20.103(c), use of respiratory protective equipment was not in accord with Regulatory Guide 8.15, "Acceptable Programs for Respiratory Protection" in that a half-mask respirator was used with head straps over the hard hat which prevented straps from lying in their normal position next to the head as required by Section 13.5 of NUREG-0041, which is referenced in Section C.8.n of Regulatory Guide 8.15.

This is an infraction.

7908240 232

775 350