

LICENSEE EVENT REPORT

EXHIBIT A

CONTROL BLOCK:  1  2  3  4  5  6  7  8  9  10 (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 2 3 4 5 6 7 8 9  
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40  
 A R A N 0 2 0 0 - 1 0 0 0 0 0 - 0 0 4 1 1 1 1 4

LICENSEE CODE LICENSE NUMBER LICENSE TYPE CAT 58

CON'T

0 1 2 3 4 5 6 7 8 9  
 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40  
 L 0 5 0 0 0 3 6 8 0 8 0 4 7 9 0 8 3 0 7 9

REPORT SOURCE DOCKET NUMBER EVENT DATE REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During Mode 1, power escalation testing, it was discovered that full  
 0 3 | length CEA #39 would not move. With the CEA inoperable due to causes  
 0 4 | other than that causing mechanical interference, and being within its  
 0 5 | alignment requirements, operation in Mode 1 continued per T.S. 3.1.3.1.C.  
 0 6 | There have been no similar occurrences.  
 0 7 | Reportable per T.S. 6.9.1.9b.  
 0 8 |

0 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
 R B E E C R D R V E Z Z  
 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE  
 LER NO. REPORT NUMBER EVENT YEAR SEQUENTIAL REPT. NO. OCCURRENCE CODE REPORT TYPE REVISION  
 A Z Z Z 0 0 0 0 N N N C 4 9 0  
 ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-4 FORM 508 PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | Investigation revealed a failed CEA enable card. The card was replaced  
 1 1 | and CEA #39 was successfully stroke tested. The CEA was declared  
 1 2 | operable within approximately one hour of the failure detection.  
 1 3 |  
 1 4 |

1 5 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
 B 0 5 0 PWR Esc. Testing A NA  
 FACILITY STATUS POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION  
 Z Z NA NA  
 RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE  
 0 0 0 Z NA  
 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION  
 0 0 0 Z NA  
 PERSONNEL INJURIES NUMBER DESCRIPTION  
 0 0 0 NA  
 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION  
 Z NA  
 PUBLICITY ISSUED DESCRIPTION  
 N NA

NAME OF PREPARER: Chris N. Shively PHONE: 501/968-2519

7909040 55/90-013